Ackerman, Joyce

1902074 - R8 SDMS

From:

Stovall - CDPHE, Curtis < curtis.stovall@state.co.us>

Sent:

Monday, November 6, 2017 11:38 AM

To:

Dave Stewart, P.E.

Cc:

Walker - CDPHE, David; Ackerman, Joyce; MacGregor - CDPHE, Kelly; Richard Dean

Subject:

Neuhauser Landfill - NGPRS Report

Dave,

The purpose for my call this morning was to follow-up on our brief discussion last Monday during the site visit. The Division would like to schedule a meeting or conference call with NGPRS and you to discuss the EM61 investigation and reporting. Here is a preview of some of our questions/comments:

- 1. Based on the drawings, the entire waste footprint in both areas (Area 1 and 2) was not covered by the EM61 survey. Why?
- 2. Why were certain anomaly locations ruled out as not likely indicative of drums?
- 3. Why is a 15-foot line spacing deemed adequate?
- 4. Was the survey conducted in a grid or was it conducted only in single-direction lines?
- 5. Why weren't the survey lines/grid plotted for the drum investigation? They were only plotted for the bedrock investigation.
- 6. At the bottom of page 2, the report states that Channel 1 was selected because it provides the deepest exploration depth. What is the exploration depth in waste areas?
- 7. The second bullet item on page 3 seems to rule out anomalies in the central portion of the landfill. Why? What is the basis for this?
- 8. The second bullet on page 3 seems to identify 4 anomaly locations, while Exhibit A-2 seems to identify 5 locations.
- 9. Test pits are not plotted on any drawing so it's unclear which anomalies (and to what extent those anomalies) were investigated.
- 10. What do the red dots and violet-colored areas represent on Exhibit A-1?
- 11. The staked area in the field near MW-2 seems to be much smaller than the anomaly area. Why?

We look forward to discussing these issues with you.

Thanks, Curt

Curt Stovall, P.E.
Environmental Protection Specialist
Solid Waste Permitting Unit
Solid Waste and Materials Management Program



P 303.692.2295 | F 303.759.5355

4300 Cherry Creek Drive South, Denver, Colorado 80246-1530 curtis.stovall@state.co.us | www.colorado.gov/cdphe/hm